

# **Dow Chemical** 2016 Review for EMT

21st March 2017

Dow.com

#### Industrial Precinct – Update

- Enviropacific Services (EPS) occupies a block of land (formerly the polystyrene plant) on the south-eastern end of the site.
- Asbestos removal of the existing warehouse facility and office building was safely and successfully completed by 1Q2016.
- Successful installation of fibreglass sheeting on warehouse facility
- Construction is ongoing to set up the soil treatment facility.





## Operational Highlights 2016

- <u>Environment</u> Recipe optimization
- <u>Personal Safety</u> fresh eye assessment in response to Dow global learning experiences.
- <u>Personal safety</u> Use of SCBA for unloading activities
- Major shutdown of manufacturing plants for maintenance. It was completed safely.







# **2016 Personal Safety & LOPC Performance**

#### **Personal injury**


- One recordable injury in 2016.
- Contractor slipped and twisted his ankle on uneven surface resulting in a Restricted Work Case.

#### **Loss of Containment:**

• **ZERO** recordable containment loss event in 2016.



# 2016 Personal Injury & Containment Loss Performance







## 2016 Regulatory Compliance

#### EPA:


- Groundwater clean-up notice continues for remediation activities.
- Major Industry Assessment completed and draft report released in March 2017.

#### Worksafe:

- No reportable event
- One improvement notice issued to do with cathodic protection.




## Resource Efficiency - Energy







# Resource Efficiency – Greenhouse Gas





#### **Resource Efficiency – Water**







### 2017 Improvement Plan

- 1. Safety Case 2017
  - a. Comprehensive evaluation of potential major incidents and control measures
  - b. Review of Emergency Response Plan
- 2. Installation and commissioning of new loading gantry
  - a. New gantry cage design incorporating "removable floor" to eliminate uneven surface.
- 3. Engineering improvement to increase plant operational and environmental performance.
- 4. Complete noise and asbestos survey







