


Qenos

2018 Noise EIP update




13/2/2018



## Noise abatement projects have all been completed

Abatement project	Due	Completed
Furnace F-651 burner noise abatement	2017	2016
Deaerator steam vents	2015	2015
Steam header vents	2015	2015
RX1 gearbox replacement	2015	2016
RX2 gearbox replacement	2015	2015
RX gearbox acoustic cover replacement	2015	2016






# Noise monitoring locations

## Charles Road Monitoring

- Noise levels have met noise EIP target in all 2017 monitoring




4



## Galvin St Monitoring

- Extended monitoring round in November and December 2017, met EIP target.
- Monitoring history is from three different locations.
  - Current location not available in future as tenant vacating premises.
- Galvin St Area is subject to a number of nearby noise sources.



5



## Next Steps

- Compile 2017 Noise EIP report
- Charles Road data demonstrates compliance with all 2017 data meeting noise EIP target
- Galvin St further monitoring needed to confirm noise EIP target achieved.
  - LA90 data consistently meets target.
- Develop 2018 noise monitoring program to close out noise EIP.

